





















 12x T02	 12x T01	 8x28 16x D01	 1x F01	 1x F11	 18x R01
 16x E01	 5x S01	 1x P01	 4x13 2x W07	 3,5x15 16x W03	 1x E02
 8x Z04	 KR-15 8x Z01	 2x U01	 4x25 4x W01		




NR	DIM	QTE	COLLI
1A	1953x345x15	1	2/2
2A	1953x345x15	1	2/2
3A	720x352x22	1	1/2
4A	689x323x15	1	1/2
5A	1877x708x2	1	2/2
6	689x80x15	1	1/2
7A	689x296x15	4	1/2
8A	689x296x15	1	1/2
9	1867x341x15	2	2/2




# 1


5X		12X		16X		8X		8X		16X	
	S01		T01		D01		Z04		Z01		W03






2




3





## 4








## 5




**A=B**



# 6

 16x E01	 4x13 2x W07	 1x P01	 1x F11	 1x F01
--	---	--	---	---



A collection of safety and warning icons. It includes a yellow triangle with an exclamation mark, a warning symbol with a hand and a screwdriver, a warning symbol with a hand and an eye, and a warning symbol with a hand and a screwdriver. There are also two icons showing a box with a warning symbol and a hand holding a screwdriver.

# 7

