






Ax20

Bx20

CØ8x30x10

Dx6

Z1x4

Z2x2

Rx2

F14,0x30x4

Ex12

F3,5x15x12

H2x5

Nx20

Tx14


Jx5

x2


0 mm 10 20 30 40 50 60

31	x1	ca. 706 x 184 x 16	1/1
32	x1	ca. 706 x 184 x 16	1/1
33	x1	ca. 618 x 167 x 16	1/1
34	x1	ca. 485 x 167 x 16	1/1
35	x1	ca. 485 x 167 x 16	1/1
36	x1	ca. 618 x 183 x 16	1/1
37	x1	ca. 618 x 183 x 16	1/1



38	x1	ca. 630 x 499 x 3	1/1
39	x1	ca. 630 x 184 x 3	1/1
40	x2	ca. 150 x 160 x 16	1/1
41	x1	ca. 282 x 160 x 16	1/1
42	x1	ca. 520 x 297 x 16	1/1
43	x2	ca. 520 x 173 x 16	1/1





1/1







1






2



3






4





5

- | | | |
|--|--|--|
| B | C | E |
|  |  |  |
| x4 | x2 | x4 |






6


- | | |
|---|---|
| Z1 | F |
|  |  |
| x4 | x8 |






7




8






9





10





11





12



$a=b$



13



14

